ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
DASARAHALLI	12	Shettihalli
Street ID	**Street Name**	**Significant Landmark**
W0125, W0158, W0127, W0160, W0147	Veera Anjaneya Temple Rd, NA	Abbigere Village High tension road
Segment No.	**Total Length (m)**	
12/C-W0125/S124604	243.29	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	181.96	77.522757	13.076166	77.521638	13.074989	W0125	W0125
2	38.72	77.520429	13.077203	77.520371	13.076858	W0127	W0127
3	22.61	77.520147	13.077242	77.520117	13.077040	W0147	W0147

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Restoration of Road cut portion done by BWSSB in Abbigere Village F bus stop surrounding Area in Ward No.12 Shettyhalli Sub Division PkG 01	9990000	2019
Year	**Type of Work**	**Other Work Type**
2018 - 2019	Others	
Tender	**Work Details**	**Job No. / Work Code**
Tender		012-19-000063
Work Order No.	**Work Order Date**	**Period of Extention**
EE?DD/WO/386/19-20	23/08/2019	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
13/01/2020	13/01/2021	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
Professional Global Infrastructure Pvt Lts		4266678.00
Phone No.	**E-Mail ID**	
9900510303		

Scanned by CamScanner

Field Inspection Details

Number of Trees	Any Other Information
2	hightention line road Abbigere
Date of Inspection	Remarks
16/01/2020	

Name: abbigere village

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Footpath Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark

Scanned by CamScanner